DPS-5294 V Copy_of 5

31 October 1958

MEMORANDUM FOR

: Special Assistant to the Director

for Planning and Development

THROUGH

: Director of D&P/DCI

25X1A

25X1A

SUBJECT

: A-9 Processing Machines a

REFERENCE :

(in 49448) 1305Z 29 Oct. 1958

- 1. Information in the above referenced message was requested after reviewing HTA's Photographic Evaluation Reports FE 206-58 and FE 207-58, on mission C 6019 flown on 10 Sept., 1958. The above reports, dated 15 Oct., 1958 reported that photographic degradation was due to, "Poor processing and film handling." They listed discrepancies as follows:
 - a. Pinholes: Numerous throughout entire mission
 - b. Abrasion and Scratches: Numerous roller abrasions and scratches throughout entire mission (processing)
 - c. Tearing (film): Numerous tears example: 690-692, 1331-1335, 1896, 2150,2212-2216, 2382, 2398 (processing)
 - d. Processing Streaks: Intermittent throughout mission
 - e. Water Spots: Water spots on entire mission; improper drying
 - f. Blistering & Frilling: Frilling 861-870, 1471 & 1473 2073-2078, 2212-2220, 2375-2376 (processing)

25X1A

25X1A

25 The above referenced message was reviewed with Lt.

of AFCIN who indicated that he found the same supply problem at during his recent trip. Lt. Col.

45 parts needed for the processor for the parts will be bought on special purchase and married to the Unit.

Approved For Rele 2000/05/04: CIA-RDP67B00 000100020018-0

25X1A also indicated that he felt the supply 25X1A had been corrected by Mr. J. Q. Reber's visit problems at on 13 Oct., 1958. (See Memo for: Special Assistant to the Director for Planning and Development, Subject: Visit to 25X1A 21 October, 1958, TSC-3964-58.) Should the supply problem still bout 12 November 25X1A exist upon arrival of the undersigned at 1958, Lt. Col. has requested that a list of parts, such as 25X1A referenced in Par. 2 above, be sent to Proj. HDQS. by message and

turned over to him for expeditious action.

25X1A Major USAF

CONCUR

25X1A

.

-2-